

Manual Supplement

| | | | |
|----------------|-----------------|-------------------|-------|
| Manual Title: | 5730A Operators | Supplement Issue: | 1 |
| Print Date: | August 2013 | Issue Date: | 10/23 |
| Revision/Date: | 2, 7/23 | Page Count: | 2 |

This supplement contains information necessary to ensure the accuracy of the above manual.
This manual is distributed as an electronic manual online at www.flukecal.com.

FLUKE®

Calibration

Change #1, 347

For firmware version 2.0.9.0 and above:

On page A-15, under **2500-Level Faults: Self Calibration**, at the end of the table, add:

| | |
|------|---|
| 2653 | Could not Cal Wideband Frequency Ratio. |
|------|---|

On page A-22, under **3800-Level Faults: Self Diagnostics (Switch Matrix)**, at the end of the table, add:

| | |
|------|---|
| 3830 | A8: K28 Relay Fault. |
| 3831 | A8: K21 Reset Relay Fault. |
| 3832 | A8: K12 & K2 Reset Relay Fault. |
| 3833 | A8: K21 Set Relay Fault. |
| 3834 | A8: K2 Set Relay Fault. |
| 3835 | A8: K12 Set Relay Fault. |
| 3836 | A8: BRF13/100 to RCL Fault. |
| 3837 | A8: K4 Set Relay Fault. |
| 3838 | A8: K6 Set Relay Fault. |
| 3839 | A8: K7 Set Relay Fault |
| 3840 | A8: K17 Reset Relay Fault. |
| 3841 | A8: K9, K13, & K14 Reset Relay Fault. |
| 3842 | A8: K9 & K14 Reset K13 Set Relay Fault. |